U.S. ENVIRONMENTAL PROTECTION AGENCY



REGION X

IDAHO OPERATIONS OFFICE 422 WEST WASHINGTON STREET BOISE, IDAHO 83702

October 10, 1989

Pat Fitch, General Manager Cyprus Thompson Creek Mine P.O. Box 62 Clayton, ID 83227

RE: NPDES Compliance Inspection Permit No. ID-002540-2

Dear Mr. Fitch:

This letter will serve as a correction to our letter of October 10, 1989, which transmitted the results of the June 27, 1989 inspection conducted at your facility.

A discussion on Monday, October 16, between Mr. Doughty and my staff brought to our attention the fact that the lab only detects to .0005 for mercury and shows values lower than that as "<.0005." My staff also misread the zinc results and erroneously concluded there was a violation for zinc. Contrary to our letter of October 10, sample results indicate compliance with current permit requirements for your facility.

We apologize for any inconvenience this misunderstanding on our part has caused.

Sincerely, Neikie arnold

Warren T. McFall Chief, Water Section

Enclosures

cc: Susan Martin, IDHW-DEQ, Boise Greg Kellogg, WD-135

1854B

AFDA		1	•	Wash	vironamental inglian, D. C	20460		1		OMB No. 2040-0003
SEPA	NI	PDE	S Co	mplia	ance Inspection Report					Approval Expires 7-31-85
				Section A	A: National		ystom			
Transaction Code	lolola	NPC 0 2 5	DES 4 0 2		8 9 0		7] 17	Inspection Type	Inspect	ctor Fac Type 2d2
		Ш	111	Ш	Remarks	1.				ШШ
Reserved Facility	Evaluatio	n Ratin	Q	71	72	2A .	73	74 75	ed	80
				Sec	tion B: Fed	cility D	eta			
Name and Location of F Cypress Mining				ompso	n Cree	ek		Entry Time AM] РМ	Pormit Effective Date 8/1/88
P.O. Box 62 Clayton, Idah								14:00 6/27	/89	Permit Expiration Date 8/2/93
Namels of On-Site Repres	entative(5)			Title(s)					Phone No(s)
Bert Doughty					Super	vis	or Ei	nvironmental	Affa	ars 838-2200
Name, Address of Respons	ible Offic	ial			Title Gener	al N	Manag	ger		
Pat Fitch				•	Phone No 838-2				-	Contacted Yes X No
ê.					Areas Evalu					
C Permit			Flow Mea			n		y, N = Not Evaluated)	S	Operations & Maintenanc
S Records/Reports		n n	Laborator			n		liance Schedules	n	Sludge Disposal
S Facility Site Review		S	Effluent/			S		Monitoring Program	n	Other:
	Sect	tion D:	Summary	of Findin	gs/Comm	A) etnor	ttach a	dditional sheets if neces	sary)	
See A	ttach	men	ts							
3										*
			* 9							*
	-				ï					*:*
								*		
			andi					8		
										0.000
Name(s) and Signature(s) of	Inspecto	r(s)	T	Agency/(Office/Tele	phone	-		10	Date

Name(s) and Signature(s) of Inspector(s)

Agency/Office/Telephone

Date
6/27/89

Signature of Reviewer

Agency/Office

Agency/Office

Date

FPA J30 + 554-1450

Regulatory/Office Use Only

Action Taken

Date

Compliance Status

Noncompliance

Compliance

Records, Reports, and Schedules Check t

A. Permit Verification

YES NO N/A	INSPECTION OBSERVATIONS VERIFY INFORMATION CONTAINED IN PERMIT	
Yes No N/A	1. Correct name and mailing address of permittee.	
Yes No N/A	2. Facility is as described in permit.	
Yes No N/A	3. Notification has been given to EPA/State of new, different, increased discharges.	
Yes No N/A	4. Accurate records of influent volume are maintained, when appropriate.	
Yes No N/A	5. Number and location of discharge points are as described in the permit.	
Yes No N/A	6. Name and location of receiving waters are correct.	
Yes (16) N/A	7. All discharges are permitted. Pit dewater discharge to Pat Hughes of	kay

B. Recordiceping and Reporting Evaluation

	be bettered as aftering wantering	
YES NO N/A	RECORDS AND REPORTS ARE MAINTAINED AS REQUIRED BY PERMIT	
No N/A	 All required information is available, complete, and current; and Information is maintained for required period. Analytical results are consistent with the data reported on the DMR's. 	
Yes No N/A	d. Results of analysis e. Dates of analysis f. Name of person performing analysis	er e
Yes No N/A Yes No N/A	5. Monitoring records are adequate and include a. Flow, pH, D.O., etc. as required by permit b. Monitoring charts	3.4
Yes No N/A	6. Laboratory equipment calibration and maintenance records are adequate.	٠
Yes No N/A	7. Plant Records are adequate* and include a. O&M Manual b. "As-built" engineering drawings c. Schedules and dates of equipment maintenance and repairs d. Equipment supplies manual e. Equipment data cards *Required only for facilities built with Federal construction grant funds.	

Records, Reports, and Schedules Check



- 8. Pretreatment records are adequate and include:
 - a. Industrial Waste Ordinance (or equivalent documents)
 - b. Inventory of industrial waste contributors, including:
 - 1. Compliance records
 - 2. User charge information

Yes No N/A

9. SPCC properly completed, when required.

Yes No N/A

10. Best Management Practices Program available, when required.

C. Compliance Schedule Status Review

YES NO N/A	THE PERMITTEE IS MEETING THE COMPLIANCE SCHEDULE	
Yes No N/A	1. The permittee has obtained necessary approvals to begin construction.	
Yes No N/A	2. Financing arrangements are complete.	
Yes No N/A	3. Contracts for engineering services have been executed.	
Yes No N/A	4. Design plans and specifications have been completed.	
Yes No N/A	5. Construction has begun.	
Yes No N/A	6. Construction is on schedule.	
Yes No N/A	7. Equipment acquisition is on schedule.	
Yes No N/A	8. Construction has been completed.	
Yes No N/A	9. Start up has begun.	
Yes No N/A	10. The permittee has requested an extension of time.	5 -
Yes No N/A	11. The permittee has met compliance schedule.	

- Records, Reports, and Schedules Checklist

D. POTW Pretreatment Requirements Review

YES NO N/A	THE FACILITY IS SUBJECT TO PRETREATMENT REQUIREMENTS
	1. Status of POTW Pretreatment Program
Yes No N/A	a. The POTW Pretreatment Program has been approved by EPA. (If not, is approved in progress?
Yes No N/A	b. The POTW is in compliance with the Pretreatment Program Compliance Schedule. (If not, note why, what is due, and intent of the POTW to remedy)
	2. Status of Compliance with Categorical Pretreatment Standards.
Yes No N/A	a. How many industrial users of the POTW are subject to Federal or State Pretreatment Standards?
Yes No N/A	b. Are these industries aware of their responsibility to comply with applicable standards?
Yes No N/A	c. Have baseline monitoring reports (403.12) been submitted for these industries?
les No N/A	i. Have categorical industries in noncompliance (on BMR reports) submitted compliance schedules?
les No N/A	11. How many categorical industries on compliance schedules are meeting the schedule deadlines?
res No N/A	d. If the compliance deadline has passed, have all industries submitted 90 day compliance reports?
es No N/A	e. Are all categorical industries submitting the required semiannual report?
les No N/A	f. Are all new industrial discharges in compliance with new source pretreatment standards?
es No N/A	g. Has the POTW submitted its annual pretreatment report?
les No N/A	h. Has the POTW taken enforcement action against noncomplying industrial users?
es No N/A	i. Is the POTW conducting inspections of industrial contributors?

Yes No N/A	3.	Are the industrial users subject to Prohibited Limits (403.5) and local limits
	1	more stringent than EPA in compliance?
1 1	1	(If not, explain why, including need for revision of limits.)
	1	The state of the s

. Facility Site Review Checklist

Yes No N/A	1. Standby power or other equivalent provision is provided.
Yes No N/A	2. Adequate alarm system for power or equipment failures is available.
Yes No N/A	3. POTW handles and disposes of sludge according to applicable Federal, State, and and local regulations.
Yes No N/A	4. All treatment units, other than back-up units, are in service.
XES No N/A	5. Procedures for facility operation and maintenance exist.
Yes No N/A	6. Organization plan (chart) for operation and maintenance is provided.
Yes No N/A	7. Operating schedules are established.
Yes No N/A	8. Emergency plan for treatment control is established.
Yes No N/A Yes No N/A Yes No N/A	9. Operating management control documents are current and include: a. Operating report b. Work schedule c. Activity report (time cards)
Yes No N/A	10. Maintenance record system exists and includes: a. As-built drawings b. Shop drawings c. Construction specifications d. Maintenance history e. Maintenance costs
Yes No N/A	11. Adequate number of qualified operators are on-hand.
Yes No N/A	12. Established procedures are available for training new operators.
Yes No N/A	 Adequate spare parts and supplies inventory and major equipment specifications are maintained.
Yes No N/A	14. Instruction files are kept for operation and maintenance of each item of major equipment.
Yes No N/A	15. Operation and maintenance manual is available.
Yes No (N/A)	16. Regulatory agency was notified of by—passing. (Dates)
) - 이 트를 통해 선생님이 사용하여 하다 마다 아이트 이 사용이 되었다. 1 전 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Facility Site Review Checklist

Yes No N/A	17. Hydraulic and/or organic overloads are experienced. Reasons for overloads	fi:
		-m
AES)NO N/A	18. Up-to-date equipment repair records are maintained.	
	19. Dated tags show out of service equipment. 20. Routine and preventive maintenance are scheduled/performed on time.	*

Permittee Sampling Inspection Checkl.

A. Permittee Sampling Evaluation

Yes No N/A	1. Samples are taken at sites specified in permit.
Yes No N/A	2. Locations are adequate for representative samples.
Yes No N/A	3. Flow proportioned samples are obtained where required by permit.
Yes No N/A	4. Sampling and analysis completed on parameters specified by permit.
Yes No N/A	5. Sampling and analysis done in frequency specified by permit.
Yes No N/A	6. Permittee is using method of sample collection required by permit. Required Method: Grab If not, method being used is: () Grab () Manual composite () () Automatic composite
Yes No N/A Yes No N/A Yes No N/A	7. Sample collection procedures are adequate: a. Samples refrigerated during compositing b. Proper preservation techniques used c. Containers and sample holding times before analyses conform with 40 CFR 136:3
Yes No N/A	8 Monitoring and analyses are performed more often than required by permit. If so, results reported in permittee's self-monitoring report.

B Sampling Inspection Procedures and Observations

Yes No N/A	1. Grab samples obtained.	- 100
Yes No N/A	2. Composite sample obtained Compositing frequency Preservation	
Yes No N/A	3. Sample refrigerated during compositing.	
Yes No N/A	4. Flow proportioned sample obtained.	
Yes No N/A	5. Sample obtained from facility sampling device.	
Yes No N/A	6. Sample representative of volume and nature of discharge.	
Yes No N/A	7. Sample split with permittee.	
Yes (No N/A	8. Chain of custody procedures employed.	

A. Flow Measurement Inspection Checklist - General

Yes No N/A	 Primary flow measuring device is properly installed and maintained.
es) No N/A	2. Flow records are properly kept.
Tes No N/A	3. Sharp drops or increases in flow values are accounted for.
Yes No N/A	4. Actual flow discharged is measured.
res No N/A	5. Influent flow is measured before all return lines.
Tes No N/A	6. Effluent flow is measured after all return lines.
Yes No N/A	 Secondary instruments (totalizers, recorders, etc.) are properly operated and maintained.
Yes No (N/A)	8. Spare parts are stocked.

B. Flow Measurement Inspection Checklist - Fluxes

Yes	No	N/A	 Flow entering flume appears reasonably well distributed across the channel and free of turbulence, boils, or other distortions.
Yes	No	N/A	2. Cross-sectional velocities at entrance are relatively uniform .
Yes	No	N/A	3. Flume is clean and free of debris or deposits.
Yes	No	N/A	4. All dimensions of flume are accurate.
Yes	No	N/A	5. Side walls of flume are vertical and smooth.
Yes	No	N/A	_6. Sides of flume throat are vertical and parallel.
Yes	No	N/A	7. Flume head is being measured at proper location.
Yes	No	N/A	8. Measurement of flume head is zeroed to flume crest.
Yes	No	N/A	9. Flume is of proper size to measure range of existing flow.
Yes	No	N/A	10. Flume is operating under free-flow conditions over existing range of flows.

				C. Flow Measurement Inspection Checklist - Wiers	
			7	1. What type of weir is being used?	
Vaa) ,;;	N/A	-	2. The weir is exactly level.	
Yes) No	N/I	A	Z. The well is exactly level.	
Yes	ON (N/A	A	3. The weir plate is plumb and its top edges are sharp and clean.	
Yes) No	N/A	A	4. There is free access for air below the nappe of the weir.	
Yeg	No	N/A	A	 Upstream channel of weir is straight for at least four times the depth of water level, and free from disturbing influences. 	r
Yes	No	N/A	1	6. The stilling basin of the weir is of sufficient size and clear of debris.	
Yes	No	N/A		7. Head measurements are properly made by facility personnel.	
Yes) No	N/A	1	8. Proper flow tables are used by facility personnel.	
			4		
				D. Flow Messurement Inspection Checklist - Other Flow Devices	
		,	7		_
				1. Type of flowmeter used:	
				2. What are the most common problems that the operator has had with the flowneter?	•
	2				
			1:		_
				3. Measured Wastewater flow:mgd; Recorded flow:mgd; Error	Z
				4. Design flow:mgd.	
Yes	Мо	N/A		5. Flow totalizer is properly calibrated.	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		1	6. Frequency of routine inspection by proper operator:/day.	
				7. Frequency of maintenance inspections by plant personnel:/year.	
				8. Frequency of flowmeter calibration:/month.	
Yes	No	N/A		9. Flow measurement equipment adequate to handle expected ranges of flow rates.	
Yes	No	N/A		10. Venturi meter is properly installed and calibrated.	
Yes	No	N/A		11. Electromagnetic flowmeter is properly calibrated.	

Laboratory	Quality	Assurance	Checklist
------------	---------	-----------	-----------

A. General

- 1	1	7	
1	Vac	M	N/A
4	100	,,,,	11/2
G	-	_	

1. Written laboratory quality assurance manual is available.

B . Laboratory Procedures

	14.0
Yes No N/A	1. EPA approved analytical testing procedures are used.
Yes No N/A	2. If alternate analytical procedures are used, proper approval has been obtained.
Yes No N/A	3. Calibration and maintenance of instruments and equipment is satisfactory.
Yes No N/A	4. Quality control procedures are used.
Yes No N/A	5. Quality control procedures are adequate.
	6. Duplicate samples are analyzed % of time.
	7. Spiked samples are used % of time.
Yes No N/A	8. Commercial laboratory is used Name <u>Analyical</u> Laboratories
	Address Boise, Idaho
	Contact
	Phone
2	

C. Laboratory Facilities and Equipment

Yes No N/A	1. Proper grade distilled water is available for specific analysis.
Yes No N/A	2. Dry, uncontaminated compressed air is available.
Yes No N/A	3. Furse hood has enough ventilation capacity.
Yes No N/A	4. The laboratory has sufficient lighting.
Yes No N/A	5. Adequate electrical sources are available.
Yes No N/A	6. Instruments/equipment are in good condition.
Yes No N/A	7. Written requirements for daily operation of instruments are available.

Laboratory Quality Assurance Checklist (comminued)

C. Laboratory Facilities and Equipment (continued)

Yes No N/A	8. Standards are available to perform daily check procedure.
Yes No N/A	9. Written trouble-shooting procedures for instruments are available.
Yes No N/A	10. Schedule for required maintenance exists.
Yes No N/A	11. Proper volumetric glassware is used.
Yes No N/A	12. Glassware is properly cleaned.
Yes No N/A	13. Standard reagents and solvents are properly stored.
Yes No N/A	14. Working standards are frequently checked.
Yes No N/A	15. Standards are discarded after recommended shelf life has expired.
Yes No N/A	16. Background reagents and solvents run with every series of samples.
Yes No N/A	17. Written procedures exist for clearup, hazard response methods, and applications—— of correction methods for reagents and solvents.
Yes No N/A	18. Gas cylinders are replaced at 100-200 psi.

D. Laboratory's Precision, Accuracy, and Control Procedures

Yes No N/A	1. A minimum of seven replicates is analyzed for each type of control check and this information is on record.
Yes No N/A	2. Plotted precision and accuracy control charts are used to determine whether valid, questionable, or invalid data are being generated from day to day.
Yes No N/A	 Control samples are introduced into the train of actual samples to ensure that valid data are being generated.
Yes No N/A	4. The precision and accuracy of the analyses are good.

poratory Quality Assurance Checklist (.cinued)

E. Data Handling and Reporting

Yes No N/A	1. Round-off rules are uniformly applied.
Yes No N/A	2. Significant figures are established for each analysis
Yes No N/A	3. Provision for cross-checking calculation is used
Yes No N/A	4. Correct formulas are used to reduce to simplest factors for quick, correct calculation
Yes No N/A	5. Control chart approach and statistical calculations for quality assurance and report are available and followed
Yes No N/A	6. Report forms have been developed to provide complete data documentation and permanent records and to facilitate data processing
Yes No N/A	7. Data are reported in proper form and units
Yes No N/A	8. Laboratory records are kept readily available to regulatory agency for required period of time
Yes No N/A	9. Laboratory notebook or preprinted data forms are permanently bound to provide good documentation
Yes No N/A	10. Efficient filing system exists enabling prompt channeling of report copies

F. Laboratory Personnel

Yes No N/A	1. The analyst has appropriate training		
Yes No N/A	2. The analyst follows the specified procedures		
Yes No N/A	3. The analyst is skilled in performing analyses		

Flow Requirement	FLOW PERMIT REQUIREMENT 3.00 T.S.S. PERMIT REQUIREMENT 30.0 T.AS. MAPLE MASUREMENT 0.490 T. Gd. MASUREMENT 0.490 T. Cd. MASUREMENT 0.0053 T. Cd. MASUREMENT 0.0053 T. Cd. MASUREMENT 0.0054 T. PD. MASUREMENT 0.0245 T. PD. MASUREMENT 0.0245 T. PD. MASUREMENT 0.0589 T. Hg. MASUREMENT 0.0589 T. Hg. MASUREMENT 0.0002 T. Zn. MAPLE MEASUREMENT 0.0002 T. Zn. MASUREMENT 0.0002 T. Zn. MASUREMENT 0.017 PERMIT REQUIREMENT 0.017 PERMIT REQUIREMENT 0.017 PERMIT REQUIREMENT 0.0165 MASUREMENT 0.0165		001		' Minimum	Average	Maximur	n : >	34					
T. S.S. MEASUREMENT T. AS. MEASUREMENT REQUIREMENT REQUIREMENT T. Gd. MEASUREMENT REQUIREMENT REQUIREMENT T. Cu. MIG/L. MEASUREMENT REQUIREMENT REQUIREMENT T. Cu. MEASUREMENT REQUIREMENT REQUIREMENT T. PD. MEASUREMENT REQUIREMENT T. PD. MARPLE MEASUREMENT REQUIREMENT T. Hg. MIG/L.	T.S.S. PERMIT PROUVEMENT REQUIREMENT REQU		1	PERMIT REQUIREMENT			.001 M	GD						
REQUIREMENT T. AS. Mg/L PERMIT REQUIREMENT REQUIREMENT T. Cd. MASUREMENT REQUIREMENT REQUIREMENT T. Cu. SAMPLE MASUREMENT REQUIREMENT REQUIREMENT T. Cu. SAMPLE MASUREMENT REQUIREMENT C. 0.0 1 T. Cu. MSAUREMENT REQUIREMENT C. 0.0 5 T. Pb. MASUREMENT REQUIREMENT T. Hg. MASUREMENT REQUIREMENT C. 0.0589 T. Hg. SAMPLE MASUREMENT PERMIT REQUIREMENT D. 0.0002 T. Zn. MG/L. MASUREMENT PERMIT REQUIREMENT REQUIREMENT PERMIT REQUIREMENT T. Zn. MASUREMENT MASUREMENT PERMIT REQUIREMENT PERMIT REQUIREMENT T. Co. 165 MASUREMENT PERMIT REQUIREMENT T. Co. 165 MASUREMENT PERMIT REQUIREMENT PERMIT REQUIREMENT T. Co. 165 MASUREMENT T. Co. 165 MASUREMENT PERMIT REQUIREMENT T. Co. 165 MASUREMENT T. Co. 165	T. AS. MRASUREMENT PERMIT PE				T		3.0							
MASUREMENT PERMIT REQUIREMENT T. Cd. MEASUREMENT PERMIT 0.490 T. Cd. MEASUREMENT 0.001 T. Cu. SAMPLE MEASUREMENT 0.0053 T. Cu. MASUREMENT 0.0245 T. Pb. MEASUREMENT 0.0245 T. Pb. MEASUREMENT 0.0589 T. Hg. MEASUREMENT 0.0589 T. Hg. SAMPLE MEASUREMENT 0.0005 T. Zn. MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.017 PERMIT REQUIREMENT 0.0165 SAMPLE MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.0165 SAMPLE MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.0165 SAMPLE MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.000	T. AS. mg/L sample measurement femilt femi		T.S.S.				30.0		001 889					
T. Cd. MEASUREMENT	REQUIREMENT 0.490 T. Cd. MASSARPLE SAMPLE MEASUREMENT 0.0053 T. Cu. SAMPLE MEASUREMENT 0.0053 T. Cu. MEASUREMENT 0.0245 T. Pb. MEASUREMENT 0.0245 T. Pb. MEASUREMENT 0.02589 T. Hg. MEASUREMENT 0.00589 T. Hg. MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.017 PERMIT REQUIREMENT 0.017 PERMIT REQUIREMENT 0.017 PERMIT REQUIREMENT 0.0165 SAMPLE MEASUREMENT 7.0 OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOATSOL COLOR OTHER MEASUREMENT 0.022NTU none none none OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOATSOL COLOR OTHER PLANTS OF THE PLAN				r									
T. Cd. MEASUREMENT C.001 T. Cu. MEASUREMENT C.005 T. PERMIT REQUIREMENT C.005 T. Hg. MEASUREMENT C.005 T. Hg. MEASUREMENT C.005 T. Hg. MEASUREMENT C.0005 T. Hg. MEASUREMENT C.00002 T. Zn. MEASUREMENT C.0002 T. Zn. MEASUREMENT C.0002 T. Zn. MEASUREMENT C.017 MG/L. PERMIT REQUIREMENT C.017 MG/L. PERMIT REQUIREMENT C.017 MG/L. PERMIT REQUIREMENT C.017 MEASUREMENT C.0165 DOUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FLOAT SOL COLOR OTHER OO1 NONE C.COMPLETE AS EXPROPRIATE FOR AMPLIES FLOAT SOL COLOR OTHER (Sections M and N: Complete as Expropriate for sampling Inspections)	T. Cd. Measurement		шg/ц .				.:		•					
T. Cu. mg/L SAMPLE COLOR DEPART	REQUIREMENT T. CU. SAMPLE MEASUREMENT PERMIT REQUIREMENT T. Pb. MEASUREMENT DO 11 MEASUREMENT MEAS						<.001			45				
T. Cu. mg/L SAMPLE MEASUREMENT	T. CO. Mg/L PERMIT REQUIREMENT T. Pb. MEASUREMENT MEASUREMENT MEASUREMENT REQUIREMENT T. Hg. MEASUREMENT MEASURE		mg/L.	PERMIT			0.0053			and the second				
T. Pb. MEASUREMENT	T. Pb. Measurement													
T. Pb. mg/L. PERMIT REQUIREMENT 0.0589 T. Hg. mg/L. PERMIT REQUIREMENT 0.0002 T. Zn. mg/L. PERMIT REQUIREMENT 0.017 PERMIT REQUIREMENT 0.017 PERMIT REQUIREMENT 0.0165 SAMPLE MEASUREMENT 0.0165 PERMIT REQUIREMENT 0.0165 OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER 0.01 none 0.22NTU none none 0.22NTU none none 0.22NTU none none 0.22NTU none none	T. Pb. MEASUREMENT		mg/L				0.0245							
T. Hg. MEASUREMENT	T. Hg. SAMPLE MEASUREMENT C.0005 //S Nouns Lab goes T. Hg. Measurement C.0005 //S Nouns Lab goes T. Zn. SAMPLE MEASUREMENT C.017 TREQUIREMENT C.0.165 T. Zn. SAMPLE MEASUREMENT C.0.165 PERMIT REQUIREMENT C.0.165 T. Zn. Measurement C.0.165 T. Zn. Measur						< .005	1		`				
T. Hg. mg/L. PERMIT REQUIREMENT T. Zn. mg/L. PERMIT REQUIREMENT PERMIT REQUIREMENT PERMIT REQUIREMENT PERMIT REQUIREMENT OUTFALL NO. OIL SHEEN GREASE O01 none O01 none O02 NS Now As Lab goes O.0002 T. Zn. MEASUREMENT O.017 PERMIT REQUIREMENT O0 9.0 OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER O01 none O022NTU none O01 none (Sections M and N: Complete as appropriate for sampling inspections)	T. Hg. MEAUREMENT 0.0005 IS Now Deep Copes		mg/L.				0.0589		,	· · ·				
T. Zn. MEASUREMENT 0.0002 T. Zn. MEASUREMENT 0.017 PERMIT REQUIREMENT -0.165 PH PERMIT REQUIREMENT 7.0 PERMIT REQUIREMENT 6.0 9.0 OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER 001 none 0.22NTU none none 1	REQUIREMENT T. Zn. Mg/L. SAMPLE MEASUREMENT PERMIT REQUIREMENT PERMIT REQUIREMENT 1.0.165 OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER OO1 none none 0.22NTU none none none (Sections M and N: Complete as appropriate for tampling inspections) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow proposite obstained flow proposite obstained flow propositions observations (Further explanation attached flow propositions) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow propositions) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow proposition observations (Further explanation attached flow proposition observations) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow proposition observations) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow proposition observations) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow proposition observations) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow propositions) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow propositions) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow propositions) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached flow propositions)	J					·<.0005	05 Its low 15 L		es .				
T. Zn. mg/L. PERMIT	T. Zn. mg/L. PERMIT REQUIREMENT	X.					0.0002		1 2					
PH SAMPLE MEASUREMENT PERMIT REQUIREMENT OUTFALL NO. OIL SHEEN GREASE TURBIDITY OUTFALL NO. OIL SHEEN ONE OF TURBIDITY OU	PH SAMPLE MEASUREMENT PERMIT REQUIREMENT 6.0 9.0 OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER OO1 none none 0.22NTU none none none (Sections M and N: Complete as appropriate for sampling inspections) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached	~					.017							
PH PERMIT REQUIREMENT 6.0 OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER OO1 none none 0.22NTU none none none (Sections M and N: Complete as appropriate for sampling inspections)	PH MEASUREMENT FROM PERMIT FROM PERMIT FOAM PERMIT PERMIT PERMIT FOAM PERMIT	\sim	mg/L.				-0.165		•					
PERMIT REQUIREMENT 6.0 9.0 OUTFALL NO. OIL SHEEN GREASE TURBIDITY FOAM FLOAT SOL COLOR OTHER OO1 none none 0.22NTU none none none (Sections M and N: Complete as appropriate for sampling inspections)	GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER OUTFALL NO. OIL SHEEN GREASE TURBIDITY VISIBLE FOAM FLOAT SOL COLOR OTHER OO1						7.0		*					
OUTFALL NO. OIL SHEEN GREASE TURBIDITY FOAM FLOAT SOL COLOR OTHER 1001 none none 0.22NTU none none none (Sections M and N: Complete as appropriate for sampling inspections)	OUTFALL NO. OIL SHEEN GREASE TURBIDITY FOAM FLOAT SOL COLOR OTHER 001	WAS BEEN A			6.0		9.0	•	•					
001 none none 0.22NTU none none none (Sections M and N: Complete as appropriate for sampling inspections)	O01 none none 0.22NTU none none none (Sections M and N: Complete as appropriate for sampling inspections) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached		OUTFALL NO.	11-40-41-41-41-41-41-41-41-41-41-41-41-41-41-	GREASE	TURBIDITY			COLOR	OTHER				
(Sections M and N: Complete as appropriate for sampling inspections)	(Sections M and N: Complete as appropriate for sampling inspections) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached	[001		none	0.22NTU	none	none	none					
(Sections M and N: Complete as appropriate for sampling inspections)	(Sections M and N: Complete as appropriate for sampling inspections) SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached	. [=		ï				1				
	SECTION M - Sampling Inspection Procedures and Observations (Further explanation attached	Γ		•	;					1				
	GRAB SAMPLES OBTAINED COMPOSITE OBTAINED FLOW PROPORTIONED SAMPLE AUTOMATIC SAMPLER USED SAMPLE SPLIT WITH PERMITTEE CHAIN OF CUSTODY EMPLOYED SAMPLE OBTAINED FROM FACILITY SAMPLING DEVICE COMPOSITING FREQUENCY	- h												
	FLOW PROPORTIONED SAMPLE AUTOMATIC SAMPLER USED SAMPLE SPLIT WITH PERMITTEE CHAIN OF CUSTODY EMPLOYED SAMPLE OBTAINED FROM FACILITY SAMPLING DEVICE COMPOSITING FREQUENCY													
Vigation through a transport of the National Assets and the National Assets an	SAMPLE SPLIT WITH PERMITTEE CHAIN OF CUSTODY EMPLOYED SAMPLE OBTAINED FROM FACILITY SAMPLING DEVICE COMPOSITING FREQUENCY PRESERVATION PRESERVATI				LE									
COMPOSITE OBTAINED	CHAIN OF CUSTODY EMPLOYED SAMPLE OBTAINED FROM FACILITY SAMPLING DEVICE COMPOSITING FREQUENCY PRESERVATION FRESERVATION		- AUTOMATI	C SAMPLER USED										
COMPOSITE OBTAINED FLOW PROPORTIONED SAMPLE	CHAIN OF CUSTODY EMPLOYED SAMPLE OBTAINED FROM FACILITY SAMPLING DEVICE COMPOSITING FREQUENCY PRESERVATION FRESERVATION		SAMPLE SP	LIT WITH PERMIT	TEE		-							
COMPOSITE OBTAINED FLOW PROPORTIONED SAMPLE AUTOMATIC SAMPLER USED	COMPOSITING FREQUENCY PRESERVATION	i												
COMPOSITE OBTAINED FLOW PROPORTIONED SAMPLE AUTOMATIC SAMPLER USED SAMPLE SPLIT WITH PERMITTEE	SAMPLE REFRIGERATED DURING COMPOSITING: THE	1	SAMPLE OF	TAINED FROM FA	ACILITY SAMPLIN	G DEVICE								
COMPOSITE OBTAINED FLOW PROPORTIONED SAMPLE AUTOMATIC SAMPLER USED SAMPLE SPLIT WITH PERMITTEE CHAIN OF CUSTODY EMPLOYED	The composition of the compositi	20	OMPOSITING FI	REQUENCY			PRESE	RVATION						
COMPOSITE OBTAINED FLOW PROPORTIONED SAMPLE AUTOMATIC SAMPLER USED SAMPLE SPLIT WITH PERMITTEE CHAIN OF CUSTODY EMPLOYED SAMPLE OBTAINED FROM FACILITY SAMPLING DEVICE		54	AMPLE REFRIG	ERATED DURING	COMPOSITING:	DYES D	NO .							
COMPOSITE OBTAINED FLOW PROPORTIONED SAMPLE AUTOMATIC SAMPLER USED SAMPLE SPLIT WITH PERMITTEE CHAIN OF CUSTODY EMPLOYED SAMPLE OBTAINED FROM FACILITY SAMPLING DEVICE COMPOSITING FREQUENCY	DAMPLE REPRESENTATIVE OF VOLUME AND HATORE OF DISCHARGE	54	AMPLE REPRES	ENTATIVE OF VO	LUME AND NATU	RE OF DISCHAR	GE							

9	Point	PERMIT	The transfer	Average	Maximu			
	002	REQUIREMENT		1	.414 M	IGD		
	T.S.S.	SAMPLE MEASUREMENT			6.0			
		PERMIT REQUIREMENT			30.0	3	· Ti-Line	
	T. As.	SAMPLE MEASUREMENT			<:.01			
	mg/L·	PERMIT REQUIREMENT			0.490		• •	
	TCd.	SAMPLE MEASUREMENT			<.001			
	mg/L	PERMIT			0.0053			
	T. Cu.	SAMPLE MEASUREMENT	-		< .01			
	mg/L	PERMIT REQUIREMENT			0.0245		31	
	T. Pb.	SAMPLE MEASUREMENT			< .01	1		
	mg/L	PERMIT REQUIREMENT			0.0589		· ;	
J	T. Hg. mg/L	SAMPLE MEASUREMENT			<.0005	A 100	was lab	Soes
		PERMIT REQUIREMENT	12		0.0002	1 .	1 1	
1X	T. Zn.	SAMPLE MEASUREMENT			.032	1		
	mg/L	PERMIT REQUIREMENT			- 0.165		•	
		SAMPLE MEASUREMENT			7.8		*	
HALL	PH 5	PERMIT REQUIREMENT	6.0		9.0			
0	UTFALL NO.	OIL SHEEN	GREASE	TURBIDITY	VISIBLE FOAM	VISIBLE FLOAT SOL	COLOR	OTHE
	002	none	none	0.4 NTU	none	none	none	
		=	1	1				7.5
		•						1
				N: Complete as app				
-		PLES OBTAINED	edures and Obse	rystions (Further ex	planation attached			
	COMPOSITI							
- ()	FLOW PRO	PORTIONED SAMP	.€					
	30 NAMES OF THE OWN	C SAMPLER USED						
- 1		LIT WITH PERMITT						
	LI CHAIN OF	CUSTODY EMPLOY	ED			45		
į į		**************************************	CH ITY CAMEL	NG DEVICE				
1	SAMPLE OF	STAINED FROM FA		NG DEVICE	POFCE	RVATION		

Outfa 003	PERMIT REQUIREMENT				16							
Turbid		Sc w Ck Bruño Ck.	Bruno Ck	Squaw Ckerdis	charge							
Turbid	SAMPLE MEASUREMENT											
-	lity PERMIT REQUIREMENT	N.A.	N.A.	N.A.		*						
1.5	SAMPLE MEASUREMENT	7.48	6.8	7.5								
PH	PERMIT	N.A.	N.A.	N.A.		•	2 10					
	SAMPLE MEASUREMENT					at .	9					
	PERMIT REQUIREMENT											
:	SAMPLE MEASUREMENT											
Ĺ	PERMIT REQUIREMENT											
-	SAMPLE MEASUREMENT											
	PERMIT					E .						
	SAMPLE MEASUREMENT			ŀ		•						
22	PERMIT REQUIREMENT					: 2	- 4					
	SAMPLE MEASUREMENT				1		<u>≓ 59</u>					
	PERMIT REQUIREMENT			-		•						
	SAMPLE MEASUREMENT											
\$ #	PERMIT REQUIREMENT	* :	3			1.						
OUTFALL N		GREASE	TURBIDITY	FOAM	VISIBLE FLOAT SOL	COLOR	OTHER					
003	none	none	n.28 .	none	none	none						
	=		ï				1.5					
	•	•										
		(Sections M and N				şa.						
	Sampling Inspection Pro	cedures and Observ	rations (Further ex	eplanation attache	<u>a</u>							
	SAMPLES OBTAINED	-										
	SITE OBTAINED	elocae										
□ сомро	☐ FLOW PROPORTIONED SAMPLE											
COMPO	□ AUTOMATIC SAMPLER USED											
COMPO		SAMPLE SPLIT WITH PERMITTEE										
COMPO	E SPLIT WITH PERMIT											
COMPO	E SPLIT WITH PERMIT OF CUSTODY EMPLOY	rED			t n	(E						
COMPO	E SPLIT WITH PERMIT OF CUSTODY EMPLOY E OBTAINED FROM FA	rED	G DEVICE		e e	(p)						
COMPO	E SPLIT WITH PERMIT OF CUSTODY EMPLOY	CILITY SAMPLIN	1400 700	PRES	SERVATION							